
wiTECH Loads to a Blank Page

1060 Chris Ordner Fri, Oct 25, 2024 wiTECH 2.0 Public Articles - Aftermarket, wiTECH 2.0 Public Articles - Dealers 4473

Problem: When attempting to load the wiTECH 2 website, the browser loads wiTECH to a blank page.





Cause: Your browser is out-of-date and is no longer supported by wiTECH.

Resolution: Update your browser to the most recent supported version. Please see the KB, wiTECH Supported Web Browsers .

If you verified your browser is supported and is up-to-date and you're still encountering issues, please contact wiTECH Support .

Online URL: https://kb.fcawitech.com/article/witech-loads-to-a-blank-page-1060.html