How-to Flash with Enhanced DRB III Emulator

552 Chris Ordner Tue, Jul 9, 2019 Enhanced DRB III Emulator, TechTOOLS 12209

- 1. Open the latest version of TechTOOLS
- 2. Search by VIN or YME
- 3. Select the "DRB III Emulator" checkbox
- 4. Select the desired flash
- 5. Select "Download / Update"

The Data Collect of Lines 1: Lines Collect Decise Status: END Not Control Part Not Status: END Not S	🔬 TechTOOLS R10.01						
Mile Status (Mile Margel): Control of Control (Mile Control (Mile) Control of Control (Mile) Control (Mile	Eile Device Options	<u>l</u> elp					
True True relations Virtual Control Parts Online Parts Online Parts Online Virtual Control Parts Online Parts Online Parts Online Parts Online Parts Online Service Buildein Number Service Buildein Number Service Buildein Number Service Buildein Online Online Service Buildein Control Service Buildein Description Service Buildein Contr	VIN : Mileage : Controller Part Number(Device DRB III DRB III Templa Templa	Status : DRB Not Connected Available Version : 64.10 Current Version : ate Version: 2006-11-03 07:25
Controller identification Method Veride Clinica Ver	Flash Templates L	ive Display Recordings					
Wile DOTHUI32230156099 Part Number Service Buildein Othera Mode DR - RAM 1500 PICKUP Image: Service Buildein Othera Service Buildein Othera Available Elisthes for 2002 DR - RAM 1500 PICKUP 5.9L 8 CYL (MP) LT/DUTY Image: Service Buildein Stars for 2002 DR - RAM 1500 PICKUP 5.9L 8 CYL (MP) LT/DUTY Available Elisthes for 2002 DR - RAM 1500 PICKUP 5.9L 8 CYL (MP) LT/DUTY Image: Service Buildein Stars for 2002 DR - RAM 1500 PICKUP 5.9L 8 CYL (MP) LT/DUTY Store Dotted Buildein / Contenser Fain Information Exprise Buildein / Contenser Fain Informatice Dut 7.0 Coper Fuse 2005.01-12.30 Mode ZCRVS8 Image: Service Buildein Stars for 2002 DR - RAM 1500 PICKUP 5.9L 8 CYL (MP) LT/DUTY Store Dotted Exprise Buildein / Contenser Fain Information for 56028410AG supersedes : Second Scalar And 2002 DR - Buildein Rein Rein Rein Rein Rein Rein Rein R	- Controller Identification Me	ethod					
With BX250156999 Part Number Yee, 3002 Service Builetin Number With 500 PICKUP Image: Service Builetin Number Engine (St. 8 CYL (MPP) LT/DUTY Struct Update: Related Service Builetins for 56028410AG AND 2002 DRRAM 1500 PICKUP 5.9L 8 CYL (MPP) Struct Update: Related Service Builetins for 56028410AG AND 2002 DRRAM 1500 PICKUP 5.9L 8 CYL (MPP) Struct Update: Related Service Builetins for 56028410AG AND 2002 DRRAM 1500 PICKUP 5.9L 8 CYL (MPP) Struct Update: Related Service Builetins for 56028410AG AND 2002 DRRAM 1500 PICKUP 5.9L 8 CYL (MPP) Struct Update: Related Service Builetins for 56028410AG AND 2002 DRRAM 1500 PICKUP 5.9L 8 CYL (MPP) Store Update: Related Service Builetin for 56028410AG Store Builetin Aumber Hold Description 10-202 DR - Store Builetin Aumber Related Service Builetin for 56028410AG Store Builetin Aumber Related Service Builetin	Vehicle Criteria		Parts Criteria			Service Bulletin Criteria	
Yes 2002 *** Model [De: Kall 1500 PICKUP *** Engine [5:9].8 CYL (MPI) LITDUTY *** Available [Eashes for 2002 DR - RAM 1500 PICKUP 5:9].8 CYL (MPI) LITDUTY *** Story Update ***	VIN 3D7HU18Z5	2G156099		Part Number		Service Bulletin Number	
Model [DR - RAM 1500 PICKUP Engine [5 SL & CYL (MP)] LT/DUTY Sove Update: CR8 Envice Sulletin / Sove Collection Description Sove Update: CR8 Envice Sulletin / Collection Description Sove Vpdate: CR8 Envice Sulletin / Condense: And 1500 PICKUP 5.9L & CYL (MP) Sove Vpdate: CR8 Envice Sulletin / Condense: And 1500 PICKUP 5.9L & CYL (MP) Sove Vpdate: CR8 Envice Sulletin / Condense: And 1500 PICKUP 5.9L & CYL (MP) Sove Vpdate: CR8 Envice Sulletin / Condense: And 1500 PICKUP 5.9L & CYL (MP) Sove Vpdate: CR8 Envice Sulletin / Condense: And 1500 PICKUP 5.9L & CYL (MP) Sove Vpdate: CR8 Envice Sulletin / Condense: And Durability E. 2001-12:30 Sove Vpdate: Envice Sulletin / Condense: Bill Sulletin / Condense: Bill Sulletin Description Envice Provide Sulletin / Condense: Bill Sulletin Description Envice Provide Sulletin Description Envice Provide Sulletin Description Envice Provide Sulletin Description Envice Provide Sulletin Provide Sulletin Description Envice Provide Sulletin Provide Sulletin Description Envice Provide Sulletin Provide Sulle	Year 2002		<u>_</u>				
Understand Extended activity Available: Elashes for 2002 DR - RAM 1500 PICKUP 5.9L 8.CYL (MPI) LT/DUTY Stow Updates OR BI Enodor Stow Updates North Control (CCN) Stow Updates Or Control (CCN) Stow Updates North Control (CCN)	Model DR - RAM 1	500 PICKUP	-				
Available Elashes for 2002 DR - RAM 1500 PCKUP 5.9L 8 CYL (MPI) LT/DUTY Available Elashes for 2002 DR - RAM 1500 PCKUP 5.9L 8 CYL (MPI) Storutigname Control Available Elashes for 2002 DR - RAM 1500 PCKUP 5.9L 8 CYL (MPI) Storutigname Control New Part # Control Non W Part # Control Control Non W Part # Control Control Control Non W Part # Control Control Control Control Non W Part # Control Control Control Control Control Non W Part # Mile Star (in KD) Star (in KD) Control Control Non W Part # Control Control Control Control Control Control Control Struct Ball Information Control Control Control Control Control Struct Ball Information Control Control Control<	Eligine [5.32 6 CTL		<u> </u>				
Available Elashes for 2002 DR - RAM 1500 PICKUP 5 9L 8 CYL (MPI) LT/DUTY Stow Updates		Use connected vehicle		Read Part Number(s) From Vehicle			
Story lighting DBB It mutator New Yart # Calibration Sales Code Type Size (in KB) B6022410AG AutoMATIO FEDERAL EML POM 265 B6022410AG Mice 84 B4 B4 Service Builetin Description Durability # 2001-12:30 B6022410AG Mice 84 B6022410AG Secondariance Secondariance Secondariance Secondariance Secondariance B6022410AG Secondariance Secondariance B6022410AG<	Available Flashes for 20	002 DR - RAM 1500 PICKUP 5 9L 8 CYL			Pelated Service Bul	letins for 56028410AG AND 2002 DB - DAM	1500 PICKUP 5 QL 8 CYL (MPI
New Part # Calibration Sales Code Type Size (in KB) 56022410AG AUTOMATIC FEDERAL EML PCM 256 Micco2DRV38 INSTRUMENT CLUSTER (CCN) EML Micc 84 Flash Information for 56028410AG Weitige Vehicle Performance and Durability E. 2001-12-30 Flash Information for 56028410AG Second Second Second Automatic Second EML Micc 84 Second Automatic Second EML Micc 84 Flash Information for 56028410AG Second Automatic Automatic Second Automatic Second Automatic A	Show Lindates	DRB III Emulator		Select All Deselect All	Service Bulle	tin # Service Bulletin Descri	ption Date
Base with a latter out of the second seco	Now Part #	Calibration	Sales Code		08-002-03	Condenser Fan Inoperative Due To Multiple Vehicle Performance and I	D Open Fuse 2003-01-31
MICO2DRV38 INSTRUMENT CLUSTER (CCN) EML MIC B4	56028410AG	AUTOMATIC FEDERAL	EML P	CM 256	10 020 01	indupio venicio i enermaneo ana i	50100mg 2 [2007 12:00
Flash information: for 55028410AG Flash information: for 55028410AG Sep28410AC 56028410AC 56028410AE 56028410AE <tr< td=""><td>MIC02DRV38</td><td>INSTRUMENT CLUSTER (CCN)</td><td>EML</td><td>11C 84</td><td>- 1</td><td></td><td></td></tr<>	MIC02DRV38	INSTRUMENT CLUSTER (CCN)	EML	11C 84	- 1		
Plash (nformation for 56028410AG Plash (nformation for 56028410AG S6028410AA S6028410AC S6028410A							
Fish information for 56028410AG New Part # 56028410AA 56028410AA 56028410AA 56028410AA 56028410AA 56028410AA 56028410AB 56028410AB 56028410AC 56							
New Part # 56028410AG supersedes : 56028410AB 2002 DR - 5 9L 8 CYL (MPI) LT/DUTY Selection(s): 1 of 2 Download / Update Ownload / Update Close the download prompt					Flash Information	pr 56028410AG	
Selection(s): 1 of 2 Pownload /Update Open the download prompt Selection(s): 1 of 2 Pownload /Update Open the download prompt Selection(s): 1 of 2 Pownload /Update Open the download prompt Selection(s): 1 of 2 Sel					New Part # 56028	410AG supersedes :	
Selection(s): 1 of 2 Developed for a second					56028410AA		
Selection(s): 1 of 2 Provident / Lipstate O pRB III O controller O LiConnect Provident / Lipstate O pRB III O controller O LiConnect Provident / Lipstate O p					56028410AB		
Selection(s): 1 of 2 Selection					56028410AD		
Selection(s): 1 of 2 Download Update O DRS III O Controller O UConnect					56028410AE		
Selection(s): 1 of 2							
Selection(s): 1 of 2					Vehicle Descripti		
Selection(s): 1 of 2					2002 DK - 0.52 0 0	STE (MP) ENDOTT	
Selection(s): 1 of 2							
Download/Undate O BBB II O Controller O RConnect	Selection(s): 1 of 2						
Profit he down frad States close the download prompt		Download / <u>U</u> pdate	© <u>D</u> RB III © <u>C</u> ontroller © <u>U</u> Conn	ect			
	Rheat the	down Bad South	lefes close t	he download prop	nnt		- 🛃 💥 🖗 🕪 🛄 👶

7. On the same computer, launch the Enhanced DRB III Emulator from the wiTECH application

Connection Wizard							
select Tool							
ouble-click row or select tool and	press "Next". List refreshes	automatically as tools are	added or removed.				
Hide Unresponsive Devices							
Device	A Year	Body	IP Address	Worksroup	Interface	Locked	Lock Owner
RDM-WSP-08805	2011	LX	10.5.155.177		WI-FI		
RDM-WSP-18186	2013	PF	10.5.155.158		WI-FI		
wiTECH 1.0 microPod	7777	77	10.5.155.156		WI-FI		
wiTECH 1.0 microPod	7777	n	172.22.22.22		usb		
Simulated-2004.HB	2004	HB	2004.HB	2			
Simulated-2005.WK	2005	WK	2005.WK				
Simulated-2006.DR	2006	DR	2006.DR				
Simulated-2006.HB	2006	нв	2006.HB				
Simulated-2006.KJ	2006	KJ	2006.KJ				
Simulated-2006.LX	2006	LX	2006.LX				
Simulated-2006.WK	2006	WK	2006.WK				
Simulated-2007.CS	2007	cs	2007.CS				
Simulated-2007.VB	2007	VB	2007.VB				
Simulated-2007.ZH	2007	ZH	2007.ZH				
Simulated-2008.RT	2008	RT	2008.RT				
Simulated-2008.ZB	2008	ZB	2008.ZB				
Simulated-2009.HB	2009	HB	2009.HB				
Simulated-2009.JC	2009	JC	2009.JC				
Simulated-2010.PM	2010	PM	2010.PM				
Simulated-2011.DP	2011	DP	2011.DP				
Simulated-2011.LX	2011	LX	2011.LX				Transaction and the
Simulated-2012.FF	2012	FF	2012.FF				
							ATT ATT
The state of the s				1			List of the second second second
_ work in standatone mode							Modiry Location Pro
							Launch DRB III Enhanced

File Help		
Display	Keypad	
Main Menu 1. DRB III Standalone 2. Connect to TechTOOLS 3. Generic Scan Tool 4. PEP Module Tools 5. Run Memory Card Program 6. DRB Utilities 7. Vehicle Flash 8. Legacy MDS1 Support Page 1 of 1	F1 F2 F3 Enter UP En Left Right Down DVOM Yes Page	F4 nter
HELP	Read Hold No Page	Back
		3
	4 5 6	5
Exit	7 8 9	>
	Shift O Mo	ore

10. Select "Start"

Module Type: JTEC PLUS	Alt Part Number :	
Status		
Step 3.2 of 7		
Step 3.3 of 7		
Step 4 of 7	Chrysler J2534 Flash Applicat	
Step 5 of 7		
Step 6 of 7	Turn key to OFF Position	
Step 7 of 7		
Reprogramming completed	ОК	
FMS129 Ver_3		
Reprogramming		

- 12. When the flash completes, close the complete prompt.
- 13. Clear DTCs

For a video version of this procedure, please see the following article:

https://kb.fcawitech.com/secure/how-to-flash-with-drb-iii-emulator-552.html

Online URL: https://kb.fcawitech.com/article/how-to-flash-with-enhanced-drb-iii-emulator-552.html