

Vehicle Reprogramming Subscription

964 Chris Ordner Tue, Sep 28, 2021 [wiTECH 2.0 Public Articles - Aftermarket](#) 78492

Effective July 15, 2020, wiTECH 2.0 Aftermarket customers will be required to purchase Vehicle Reprogramming Subscription (“Reprogramming Subscription”) to flash Stellantis vehicles. The Reprogramming Subscription fee is \$35 per VIN for duration of one-year and it can be purchased by following the steps outlined below:

- Log-in to the Mopar Technical Service Portal (MTSP) using the following URL: <https://mopartsp.com/>
- Select “Purchase” on the left navigation bar, then "Flash Subscriptions" to purchase the Subscription(s)

After the Reprogramming Subscription is purchased, it is activated when the first flash is performed with the wiTECH 2.0 Diagnostic Application or the wiTECH 2.0 J2534 Application.

Each Reprogramming Subscription purchased allows the user to flash all ECUs requiring an update on a single VIN for duration of one-year.

When the user logs into the wiTECH 2.0 Diagnostic Application or the wiTECH 2.0 J2534 Application and accesses the Flash tab, the system will verify if the user has purchased a Reprogramming Subscription. If the user has not purchased one, wiTECH 2.0 will provide a link to the Mopar Technical Service Portal (MTSP) for the account holder to be able to purchase a Reprogramming Subscription. Please see the screenshot below:

The screenshot shows the wiTECH 2.0 Diagnostic Application interface. At the top, the vehicle information is displayed: 2019 RAM 1500 PICKUP 5.7L V8 HEMI W/ BSG (eTorque) with VIN 1C6SRFST0KN603729. The battery voltage is 12.80 Volts. Below this, the 'Action Items' section is visible, with tabs for Topology, All DTCs, All Flashes, Recalls, and RRTs. A red box highlights a message: 'Reprogramming Subscriptions are required. To purchase a Reprogramming Subscription, please click here.' Below this message is a table with columns: ECU, NEW PART NUMBER, CALIBRATION, and # OF BULLETINS. The table lists two ECUs: TCM and PCM, each with a part number, calibration information, and a dropdown menu showing '1' bulletins.

ECU	NEW PART NUMBER	CALIBRATION	# OF BULLETINS
TCM	68360080AN	2019 DT RAM 1500 5.7L TCM BSG 4WD 3.21AR NAFTA	1
PCM	68378711AM	2019 DT 5.7L PCM BSG 33GAL 3.21AR AAC NAFTA	1

NOTE: Effective July 15, 2020, the following are the Subscription requirements for performing flash with wiTECH 2.0 Diagnostic Application and wiTECH 2.0 J2534 Application

- An active wiTECH 2.0 Subscription
- An active TechAuthority Subscription
- An active Reprogramming Subscription

For a detailed VRS how-to, please see [Vehicle Reprogramming Subscription \(VRS\) - How-to](#) .

Online URL: <https://kb.fcawitech.com/article/vehicle-reprogramming-subscription-964.html>