Unable to Flash Reprogram Vehicle ECUs Using StarSCAN

846 Will Flickema Thu, Jul 5, 2018 StarSCAN 2531

ERROR MESSAGE:

• Unable to flash with StarSCAN: "Only the StarMOBILE or the wiTECH system can perform this action"

Support for StarSCAN and StarMOBILE has been discontinued. Please see the following articles for more information:

StarMOBILE Desktop Client Application Support has been Discontinued

StarSCAN Tool Support has been Discontinued

Online URL: https://kb.fcawitech.com/article/unable-to-flash-reprogram-vehicle-ecus-using-starscan-846.html